
GEORADAR S/A. Rua do Campo, 80 Vale do Sereno, Nova Lima, MG (0xx) 31 2104 - 7171	**Slug test analysis**	
	No:	
	Project: PLANGAS ADITIVO	
	Client: PETROBRAS	
Location: ARACRUZ - ES	Slug test: PL-PM 39	Test well: PL-PM 39
Test performed by: Test date: 24/8/2007	Evaluated by: ROBERTO Evaluation date: 24/8/2007	
Analysis method: Time vs. Change in waterlevel plot	Aquifer thickness:	



This document was created with Win2PDF available at http://www.daneprairie.com.
The unregistered version of Win2PDF is for evaluation or non-commercial use only.