
GEORADAR S/A. Rua do Campo, 80 Vale do Sereno, Nova Lima, MG (0xx) 31 2104 - 7171	**Slug test analysis** No: Project: PLANGÁS - BARRA DO RIACHO Client: PETROBRAS

Location: ARACRUZ / ES	Slug test: PL-SL 06	Test well: PL-SL 06

Test performed by: GEORADAR Test date: 17/8/2007	Evaluated by: RMRA Evaluation date: 17/8/2007
Analysis method: HVORSLEV	Aquifer thickness:



Conductivity: 3,55×10^-7 [m/s]

This document was created with Win2PDF available at http://www.daneprairie.com.
The unregistered version of Win2PDF is for evaluation or non-commercial use only.